

RENAULT Mégane

Located in: **Italy**

Vehicle reference:

VF1DZ1N0645850897Body type: **Coupe**Gearbox type: **Manual**Drive: **Front**Fuel type: **Petrol**Engine size: **1998 cm3**Engine power: **184 kW / 250 hp**CO2 emissions in mixed driving: **190 g/km**

Number of odometer readings: 2



Number of inspection records: 2



Total number of records: 4

Report created on:

26/03/2024 at 18:49:00

Scan QR code for [current version](#)
(available until: 25/04/2024)

Quick Check

Damage

No damage reported to CARFAX

**No issues reported**

Import

Not a private import

**No issues reported**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

No damage reported

There has been no damage reported for this vehicle



Mileage Check

Date
23/01/2018

Mileage
57 923 km



No issues indicated

The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Vehicle age



First registration date: 21/09/2011

History information

Date	Mileage	Event
21/09/2011		Registered in Italy
23/01/2018	57 923 km	Inspected in Italy Inspection passed
16/12/2020	80 543 km	Inspected in Italy
19/12/2020		New owner reported

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Petrol
CO2 emissions in mixed driving	190 g/km
EU emission standard	Euro 5
Weight	
Curb weight	1 462 kg
Max payload	373 kg
Gross vehicle weight	1 835 kg
Dimensions	
Length	4 299 mm
Width	1 848 mm
Wheelbase	2 646 mm
Other information	
European vehicle category	M1
EU standard code	e2*2001/116*0373*26
Number of doors	3
Number of seats	5

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Number of inspection records

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.