



We might have more information for this vehicle - please check the up to date version online

Your vehicle history is being collated from a vast number of sources. Some information may take up to 60 seconds to load. Scan the QR or [click here](#) to be sure of accessing all information to our availability.



Vehicle History Report



03/09/2024

NISSAN Murano

Located in: **Italy**

Vehicle reference:

JN1TBNZ51U0101111

Body type: **SUV/MPV**

Gearbox type: **Automatic**

Drive: **AWD**

Fuel type: **Diesel**

Engine size: **2488 cm3**

Engine power: **140 kW / 190 hp**

CO2 emissions in mixed driving: **210 g/km**



Number of odometer readings: 4



Number of inspection records: 4



Total number of records: 7

Report created on:

03/09/2024 at 18:06:41



Scan QR code for [current version](#)
(available until: 03/10/2024)

Quick Check

Damage

No damage reported to CARFAX



No issues reported

Import

Not a private import



No issues reported

Vincoli

Check not complete. Please refresh the report.



No data available

Ipoteca

Check not complete. Please refresh the report.



No data available

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview




No damage reported: There has been no damage reported for this vehicle

Mileage Check

Date
08/10/2021

Mileage
63 393 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Odometer

8 5 6 6 9

Last reported: 10/10/2023

Vehicle age

years
10

months
10

First registration date: 31/10/2013

Inspections



Latest inspection:
10/10/2023

Inspection due date: 31/10/2025

Owners BETA**Owner 1 in Italy**Purchase year: **2013**Length of use: **1 year 3 months**

There is no more information available about this owner.

Owner 2 in ItalyPurchase year: **2015**Length of use: **1 year 11 months**Type of owner: **Commercial business****Owner 3 in Italy**Purchase year: **2017**Type of owner: **Private individual****History information**

Date	Mileage	Event
31/10/2013		Registered in Italy
24/02/2015		New owner reported Owner type: commercial
31/01/2017		New owner reported Owner type: private individual
27/10/2017	19 650 km	Inspected in Italy Inspection passed
07/10/2019	47 655 km	Inspected in Italy
08/10/2021	63 393 km	Inspected in Italy
10/10/2023	85 669 km	Inspected in Italy Inspection valid until 31/10/2025

Based on data reviewed from 22 countries in Europe and North America

Technical details

Environment and consumption

Fuel type	Diesel
CO2 emissions in mixed driving	210 g/km
EU emission standard	Euro 5

Weight

Curb weight	1 996 kg
Max payload	499 kg
Gross vehicle weight	2 495 kg

Dimensions

Length	4 860 mm
Width	1 885 mm
Wheelbase	2 825 mm

Other information

European vehicle category	M1
EU standard code	e1*2001/116*0478*02
Number of doors	5
Number of seats	5

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.