

## HYUNDAI Santa Fe

Located in: **Italy**

Vehicle reference:

**KMHS81XDBU747488**

Body type: **Estate**

Gearbox type: **Automatic**

Drive: **AWD**

Fuel type: **Diesel**

Engine size: **2199 cm3**

Engine power: **145 kW / 197 hp**

CO2 emissions in mixed driving: **194 g/km**



Number of odometer readings: 5



Number of inspection records: 5



Total number of records: 6

Report created on:

11/07/2024 at 17:28:07



Scan QR code for [current version](#)  
(available until: 10/08/2024)

### Quick Check

#### Damage

No damage reported to CARFAX



**No issues reported**

#### Import

Not a private import



**No issues reported**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

### Damage Overview




**No damage reported:** There has been no damage reported for this vehicle

## Mileage Check

Date  
**13/05/2017**

Mileage  
**65 207 km**



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Vehicle age



First registration date: 17/05/2011

### Inspections



Latest inspection:  
17/04/2023

Inspection due date: 17/04/2025

## Owners **BETA**

### Owner 1 in Italy

Purchase year: **2011**

Length of use: **13 years 1 month**

There is no more information available about this owner.

## History information

Date	Mileage	Event
17/05/2011		Registered in Italy New owner reported

<b>Date</b>	<b>Mileage</b>	<b>Event</b>
28/05/2015	50 474 km	Inspected in Italy Inspection passed
13/05/2017	65 207 km	Inspected in Italy Inspection passed
14/05/2019	74 797 km	Inspected in Italy Inspection passed
03/05/2021	81 356 km	Inspected in Italy Inspection passed
17/04/2023	87 243 km	Inspected in Italy Inspection passed Inspection valid until 17/04/2025

Based on data reviewed from 22 countries in Europe and North America

## Technical details

### Environment and consumption

Fuel type	<b>Diesel</b>
CO2 emissions in mixed driving	<b>194 g/km</b>
EU emission standard	<b>Euro 5</b>

### Weight

Curb weight	<b>2 021 kg</b>
Max payload	<b>549 kg</b>
Gross vehicle weight	<b>2 570 kg</b>

### Dimensions

Length	<b>4 660 mm</b>
Width	<b>1 890 mm</b>
Wheelbase	<b>2 700 mm</b>

### Other information

European vehicle category	<b>M1</b>
EU standard code	<b>e11*2001/116*0270*12</b>
Number of doors	<b>5</b>
Number of seats	<b>5</b>

## CARFAX Glossary

### CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

**Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.