

**SKODA Octavia**

Located in: **Italy**

Vehicle reference:

**TMBUH61Z892030598**

Body type: **Estate**

Gearbox type: **Manual**

Drive: **Front**

Fuel type: **Diesel**

Engine size: **1968 cm3**

Engine power: **125 kW / 170 hp**



Number of odometer readings: **2**



Number of inspection records: **2**



Total number of records: **4**

Report created on:

15/06/2024 at 19:25:35



Scan QR code for [current version](#)  
(available until: 15/07/2024)

**Quick Check**

**Damage**

No damage reported to CARFAX

✔ No issues reported

**Import**

Not a private import

✔ No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

**Damage Overview**

✔ **No damage reported:** There has been no damage reported for this vehicle

**Mileage Check**



✔ **No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

**Highlights**

**Vehicle age**

years  
**14**

First registration date: 31/05/2010

**Inspections**



Latest inspection:  
22/09/2022

**Owners** BETA**Owner(s) in Italy**Purchase year: **2010**

There is no more information available about one or more consecutive owners.

**Owner(s) in Italy**Purchase year: **2010**

There is no more information available about one or more consecutive owners.

**History information**

Date	Mileage	Event
31/05/2010		Registered in Italy
22/09/2010		New owner reported
21/09/2020	54 547 km	Inspected in Italy
22/09/2022	63 946 km	Inspected in Italy

Based on data reviewed from 22 countries in Europe and North America

**Technical details****Environment and consumption**Fuel type: **Diesel**EU emission standard: **Euro 4****Weight**Curb weight: **1 515 kg**Max payload: **465 kg**Gross vehicle weight: **1 980 kg****Dimensions**Length: **4 579 mm**Width: **1 769 mm**Wheelbase: **2 575 mm****Other information**European vehicle category: **M1**EU standard code: **e11\*2001/116\*0230\*30**Number of doors: **5**Number of seats: **5**

**Inspections**

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

**Number of odometer readings**

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

**Number of records**

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

**Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.