



## CITROEN C5

Located in: **Italy**

Vehicle reference:

**VF7RDRHHADL513120**

Body type: **Sedan**

Gearbox type: **Automatic**

Drive: **Front**

Fuel type: **Diesel**

Engine size: **1997 cm3**

Engine power: **120 kW / 163 hp**

CO2 emissions in mixed driving: **163 g/km**



Number of odometer readings: 2



Number of inspection records: 2



Total number of records: 4

Report created on:

03/07/2024 at 19:24:01



Scan QR code for [current version](#)  
(available until: 02/08/2024)

### Quick Check

#### Damage

No damage reported to CARFAX



**No issues reported**

#### Import

Not a private import



**No issues reported**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

### Damage Overview



**No damage reported:** There has been no damage reported for this vehicle

### Mileage Check

Date | Mileage  
26/06/2019 | 78 952 km

km

110 000

100 000

80 000

60 000

40 000

2014

2015

2016

2017

2018

2019

2020

2021



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Vehicle age



First registration date: 24/07/2013

### Inspections



Latest inspection:  
19/07/2021

## Owners BETA

### Owner(s) in Italy

Purchase year: **2013**

There is no more information available about one or more consecutive owners.

### Owner(s) in Italy

Purchase year: **2016**

There is no more information available about one or more consecutive owners.

## History information

Date	Mileage	Event
24/07/2013		Registered in Italy
27/01/2016		New owner reported
26/06/2019	78 952 km	Inspected in Italy
19/07/2021	96 354 km	Inspected in Italy

Based on data reviewed from 22 countries in Europe and North America

## Technical details

### Environment and consumption

CO2 emissions (mixed driving)	100 g/km
EU emission standard	Euro 5
<b>Weight</b>	
Curb weight	1 684 kg
Max payload	506 kg
Gross vehicle weight	2 190 kg
<b>Dimensions</b>	
Length	4 779 mm
Width	1 860 mm
Wheelbase	2 815 mm
<b>Other information</b>	
European vehicle category	M1
EU standard code	e2*2001/116*0360*25
Number of doors	4
Number of seats	5

## CARFAX Glossary

### CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

### Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.



---

CARFAX est un fournisseur international d'historiques de véhicules dont l'objectif est de rendre le marché des voitures d'occasion plus transparent et les routes plus sûres dans le monde entier.

Surfer en toute sécurité grâce à des normes de sécurité maximales.

---

[Contact](#)

[Presse](#)

[Carrières](#) [Nous embauchons](#)

[Conditions générales](#)

---



---

[Politique de confidentialité](#)

[Connexion pour les entreprises](#)

[Personnaliser mes choix](#)

---

Copyright © 2024, CARFAX Europe GmbH