

MERCEDES CLK 220 CDI

Located in: **Italy**

Vehicle reference:

WDB2093081F219641

Body type: **Coupe**

Gearbox type: **Manual**

Drive: **Rear**

Fuel type: **Diesel**

Engine size: **2148 cm3**

Engine power: **110 kW / 150 hp**



Number of odometer readings: 3



Number of inspection records: 3



Total number of records: 4

Report created on:

03/07/2024 at 19:26:13



Scan QR code for [current version](#)
(available until: 02/08/2024)

Quick Check

Damage

No damage reported to CARFAX



No issues reported

Import

Not a private import



No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview




No damage reported: There has been no damage reported for this vehicle

Mileage Check

Date
12/10/2015

Mileage
49 400 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Vehicle age



First registration date: 03/01/2007

Inspections



Latest inspection:
25/10/2021

Owners BETA

Owner 1 in Italy

Purchase year: **2007**

Length of use: **17 years 6 months**

There is no more information available about this owner.

History information

Date	Mileage	Event
03/01/2007		Registered in Italy New owner reported

Date	Mileage	Event
12/10/2015	49 400 km	Inspected in Italy Inspection passed
01/10/2019	72 313 km	Inspected in Italy
25/10/2021	73 555 km	Inspected in Italy

Based on data reviewed from 22 countries in Europe and North America

Technical details

Environment and consumption

Fuel type	Diesel
EU emission standard	Euro 4

Weight

Curb weight	1 575 kg
Max payload	455 kg
Gross vehicle weight	2 030 kg

Dimensions

Length	4 638 mm
Width	1 725 mm
Wheelbase	2 715 mm

Other information

European vehicle category	M1
EU standard code	e1*98/14*0184*11
Number of doors	2
Number of seats	4

CARFAX Glossary

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.