



**We might have more information for this vehicle - please check the up to date version online**

Your vehicle history is being collated from a vast number of sources. Some information may take up to 60 seconds to load. Scan the QR or [click here](#) to be sure of accessing all information to our availability.



## Vehicle History Report



25/07/2024

### FORD S-MAX

Located in: **Italy**

Vehicle reference:

**WF0SXXGBWSAT76092**

Body type: **SUV/MPV**

Gearbox type: **Automatic**

Drive: **Front**

Fuel type: **Petrol**

Engine size: **1976 cm3**

Engine power: **149 kW / 203 hp**



Number of odometer readings: 5



Number of inspection records: 6



Total number of records: 8

Report created on:

25/07/2024 at 09:25:57



Scan QR code for [current version](#)

(available until: 24/08/2024)

### Quick Check

#### Damage

No damage reported to CARFAX



**No issues reported**

#### Import

Not a private import



**No issues reported**

#### Vincoli

Check not complete. Please refresh the report.



**No data available**

#### Ipoteca

Check not complete. Please refresh the report.



**No data available**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

### Damage Overview




**No damage reported:** There has been no damage reported for this vehicle

## Mileage Check

Date  
**30/04/2018**

Mileage  
**49 078 km**



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Odometer

**72532**

Last reported: 29/04/2024

### Vehicle age

years: **14**  
months: **3**

First registration date: 22/04/2010

### Inspections



Latest inspection:  
29/04/2024

Inspection due date: 30/04/2026

## Owners BETA

### Owner 1 in Italy

Purchase year: **2010**

Length of use: **8 months**

Type of owner: **Commercial business**

### Owner 2 in Italy

Purchase year: **2010**

Type of owner: **Private individual**

## History information

Date	Mileage	Event
22/04/2010		Registered in Italy New owner reported Owner type: commercial
22/12/2010		New owner reported Owner type: private individual
22/04/2014		Inspected in Italy Inspection passed
19/04/2016	35 269 km	Inspected in Italy Inspection passed
30/04/2018	49 078 km	Inspected in Italy Inspection passed
23/04/2020	57 530 km	Inspected in Italy Inspection passed
11/04/2022	66 118 km	Inspected in Italy Inspection passed
29/04/2024	72 532 km	Inspected in Italy Inspection valid until 30/04/2026

Based on data reviewed from 22 countries in Europe and North America

## Technical details

### Environment and consumption

Fuel type **Petrol**

EU emission standard **Euro 5**

### Weight

Curb weight **1 676 kg**

Max payload **729 kg**

Gross vehicle weight **2 405 kg**

### Dimensions

Length **4 772 mm**

Width **1 884 mm**

Wheelbase **2 850 mm**

### Other information

European vehicle category **M1**

EU standard code **e13\*2001/116\*0185\*10**

Number of doors **5**

Number of seats **7**

## CARFAX Glossary

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### Odometer

The number of kilometers displayed on the most recent odometer reading.

**Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

**Vincoli**

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.