



**We might have more information for this vehicle - please check the up to date version online**

Your vehicle history is being collated from a vast number of sources. Some information may take up to 60 seconds to load. Scan the QR or [click here](#) to be sure of accessing all information to our availability.



## Vehicle History Report



23/09/2024

### PEUGEOT 508

Located in: **Italy**

Vehicle reference:

**VF38URHCMGL024791**

Body type: **SUV/MPV**

Gearbox type: **Automatic**

Drive: **Front**

Fuel type: **Electric, Diesel**

Engine size: **1997 cm3**

Engine power: **120 kW / 163 hp**

CO2 emissions in mixed driving: **109 g/km**



Number of odometer readings: 3



Number of inspection records: 3



Total number of records: 6

Report created on:

23/09/2024 at 18:17:35



Scan QR code for [current version](#)  
(available until: 23/10/2024)

### Quick Check

#### Damage

No damage reported to CARFAX



**No issues reported**

#### Import

Not a private import



**No issues reported**

#### Vincoli

Check not complete. Please refresh the report.



**No data available**

#### Ipoteca

Check not complete. Please refresh the report.



**No data available**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.


### Damage Overview



**No damage reported:** There has been no damage reported for this vehicle

## Mileage Check

Date | Mileage  
09/06/2022 | 84 869 km



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Odometer

113422

Last reported: 10/06/2024

### Vehicle age

years | months  
8 | 1

First registration date: 29/07/2016

### Inspections



Latest inspection:  
10/06/2024

Inspection due date: 30/06/2026

**Owner 1 in Italy**

Purchase year:	<b>2016</b>
Length of use:	<b>2 months</b>
Type of owner:	<b>Commercial business</b>

**Owner 2 in Italy**

Purchase year:	<b>2016</b>
Length of use:	<b>less than a month</b>
Type of owner:	<b>Commercial business</b>

**Owner 3 in Italy**

Purchase year:	<b>2016</b>
Type of owner:	<b>Private individual</b>

**History information**

<b>Date</b>	<b>Mileage</b>	<b>Event</b>
29/07/2016		Registered in Italy New owner reported Owner type: commercial
05/10/2016		New owner reported Owner type: commercial
19/10/2016		New owner reported Owner type: private individual
26/06/2020	60 729 km	Inspected in Italy Inspection passed
09/06/2022	84 869 km	Inspected in Italy Inspection passed
10/06/2024	113 422 km	Inspected in Italy Inspection passed Inspection valid until 30/06/2026

## Technical details

### Environment and consumption

Fuel type	Electric, Diesel
CO2 emissions in mixed driving	109 g/km
EU emission standard	Euro 6

### Weight

Curb weight	1 845 kg
Max payload	480 kg
Gross vehicle weight	2 325 kg

### Dimensions

Length	4 828 mm
Width	1 864 mm
Wheelbase	2 817 mm

### Other information

European vehicle category	M1
EU standard code	e2*2007/46*0080*31
Number of doors	5
Number of seats	5

## CARFAX Glossary

### CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

### Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

### Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

**Number of records**

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

**Odometer**

The number of kilometers displayed on the most recent odometer reading.

**Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

**Vincoli**

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.