

AUDI A6

Located in: **Italy**

Vehicle reference:

WAUZZZ4G3CN029179

Body type: **Sedan**

Gearbox type: **Automatic**

Drive: **AWD**

Fuel type: **Diesel**

Engine size: **2967 cm3**

Engine power: **180 kW / 245 hp**

CO2 emissions in mixed driving: **156 g/km**



Number of odometer readings: 4



Number of inspection records: 4



Total number of records: 6

Report created on:

05/12/2024 at 17:48:35



Scan QR code for [current version](#)
(available until: 04/01/2025)

Quick Check

Damage

No damage reported to CARFAX



No issues reported

Import

Not a private import



No issues reported

Vincoli

No administrative detention or other liens reported for this vehicle (source ACI, information received on 05/12/2024). [What is a "Vincoli"](#)



No issues reported

Ipoteca

No "Ipoteca" reported for this vehicle (source ACI, information received on 05/12/2024). [What is an "Ipoteca"](#)



No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.


Damage Overview



No damage reported: There has been no damage reported for this vehicle

Mileage Check

Date | Mileage
07/11/2018 | 28 786 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Odometer

41745

Last reported: 14/10/2024

Vehicle age

years
12

First registration date: 15/11/2012

Inspections



Latest inspection:
14/10/2024

Inspection due date: 31/10/2026

Owner 1 in Italy

Purchase year:	2012
Length of use:	7 months
Type of owner:	Commercial business

Owner 2 in Italy

Purchase year:	2013
Type of owner:	Private individual

History information

Date	Mileage	Event
15/11/2012		Registered in Italy New owner reported Owner type: commercial
24/06/2013		New owner reported Owner type: private individual
07/11/2018	28 786 km	Inspected in Italy
03/11/2020	33 649 km	Inspected in Italy
27/10/2022	38 760 km	Inspected in Italy
14/10/2024	41 745 km	Inspected in Italy Inspection valid until 31/10/2026

Based on data reviewed from 22 countries in Europe and North America

Technical details

Environment and consumption

Fuel type	Diesel
CO2 emissions in mixed driving	156 g/km
EU emission standard	Euro 5

Weight

Curb weight	1 795 kg
Max payload	535 kg
Gross vehicle weight	2 330 kg

Dimensions

Length	4 915 mm
Width	1 874 mm
Wheelbase	2 921 mm

Other information

European vehicle category	M1
EU standard code	e1*2007/46*0436*03
Number of doors	4
Number of seats	5

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.