



Volkswagen

VIN: **WVWZZZ1KZAW141279**

Diesel

Généré le 2025-01-02 16:30



Statut légal

✓ Tout a l'air bien



Dommage

✓ Tout a l'air bien



+31

Sources de données

Nous avons vérifié 900+ sources de données dans **35 pays**

Vol

Le véhicule est-il actuellement signalé comme volé ? A-t-il été volé par le passé ? A-t-il été retrouvé ?




Aucun problème détecté

Nous n'avons trouvé aucune indication démontrant que le véhicule ait été volé.



Note

Bases de données policières. Vérification des véhicules volés effectué dans **7 pays** :  +1

Voici ce que nous avons vérifié :



Actuellement déclaré volé

✓ Aucun enregistrement trouvé



Volé par le passé

✓ Aucun enregistrement trouvé

Statut actuel inconnu



Volé puis retrouvé

✓ Aucun enregistrement trouvé

Le véhicule a été retrouvé

Base de données de la police sur les véhicules volés – **vérification effectuée en :**



États-Unis



Lituanie



Slovaquie



Statut légal

Le véhicule a-t-il passé le contrôle technique ? A-t-il été marqué comme mis à la casse ?

✓ Aucun problème détecté

Aucune information sur le statut juridique de ce véhicule n'a été trouvée.

Juridique



Contrôle technique

✓ Aucun enregistrement trouvé

Pas d'enregistrement de contrôle technique trouvé



Épave

✓ Aucun enregistrement trouvé

Rien n'indique que le véhicule a été déclaré comme épave

Dommage

Ce véhicule a-t-il été endommagé par le passé ? Quel était le montant des dommages ?

✓ Aucun problème détecté

Registre des dommages



Des inexactitudes peuvent parfois se produire, surtout lorsqu'on vérifie des véhicules plus anciens. Les ateliers de réparation clandestins peuvent déguiser illégalement les défauts et dommages d'un véhicule. Parfois, même les plaques VIN d'un véhicule peuvent être remplacées. Nous avons diverses méthodes pour détecter ces infractions, mais il est impossible de fournir une garantie à 100%.

Catastrophes naturelles

Le véhicule a-t-il été localisé dans la zone d'une catastrophe naturelle ?

✓ **Aucun problème détecté**

Le véhicule ne s'est pas trouvé dans la zone d'une catastrophe naturelle

Spécifications et équipement

Quels sont les spécifications et l'équipement connus pour ce véhicule ?

i **Note**

Vérifie que les spécifications et l'équipement de ce véhicule correspondent aux déclarations du vendeur.

Identification et spécifications techniques



Marque

Volkswagen



Type de carrosserie

Hayon



Déplacement moteur

2l



Puissance moteur
103 kW (138 hp)



Type de carburant
Diesel



Type de transmission
Manuel



Nombre de portes
4



Position du volant
Volant à gauche



Nombre de cylindres
4

Équipement

D'origine, sortie d'usine

0A2

4 DOORS

0AE

FRONT STABILIZER

0BE

REAR STABILIZER

0EN

INSTALLATION DIFFERENTIATION FOR TRANSMISSION MQ 350 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0HA

VEHICLE CLASS DIFFERENTIATION 1K0/5K0

0KA

WITHOUT DECALS AND EMBLEMS

0P1

REAR SIDE EXHAUST TAILPIPE

0TD

FLOOR MATS IN FRONT AND REAR

0VG

INFORMATION KIT IN ITALIAN

0Y1

STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1DG

NAMEPLATE SET "TDI"

1E0

WITHOUT ACTIVATED CARBON CANISTER

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1JC

REAR SHOCK ABSORPTION FOR SPORTS VERSION

1KF

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1Q1

MASS DAMPER FOR STEERING WHEEL, 26.5 HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1W2

GLOVE COMPARTMENT COOLING SYSTEM

1X1

FOUR WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2G5

FILLER NECK MODULE 1 WITHOUT INSERT

2H0

WITHOUT "DRIVE SELECT"

2JD

SPORTS BUMPERS

2KY

LABELS/PLATES IN ITALIAN, SPANISH AND PORTUGUESE

2LC

FUEL TANK WITH SPECIAL MATERIAL TREATMENT (COEXTRUSION)

2PP

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL

2UC

SPORTS VERSION

2WA

WITHOUT ADDITIONAL TIRES

3B5

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3J1

HEIGHT-ADJUSTABLE HEAD RESTRAINTS FOR FRONT SEATS

3K0

WITHOUT SAFETY HEAD RESTRAINT SYSTEM

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3SG

SPORTS COMFORT SEAT, FRONT, RIGHT

3T2

THREE REAR HEAD RESTRAINTS

3TG

SPORTS COMFORT SEAT IN FRONT, LEFT

3U1

FOLDING TRUNK COVER

3X0

WITHOUT LOAD-THROUGH HATCH

3ZB

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A0

WITHOUT SEAT HEATER

4AF

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4K3

RADIO REMOTE CONTROLLED CENTRAL LOCKING OPERATED FROM INSIDE AND SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATINGGLASS

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P0

REAR FLOOR PANEL MODULE, TYPE 1

4R4

POWER WINDOWS WITH COMFORT OPERATION ANDCIRCUIT BREAKER

4SD

VANITY MIRROR, LEFT, ILLUMINATED

4TD

RIGHT VANITY MIRROR ILLUMINATED

4U5

LUGGAGE POCKETS ON BACKREST

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5A7

COMFORT TRUNK LINING WITH SERVICE LID/ COVER

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J0

WITHOUT REAR SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MJ

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6KC

RADIATOR GRILLE

6P1

REAR LICENSE PLATE CARRIER (ECE)

6PC

HAND BRAKE LEVER HANDLE IN LEATHER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6W1

FRONT LICENSE PLATE CARRIER (LARGE)

6XG

EXTERIOR MIRRORS: WITH MEMORY FEATURE, POWER-ADJUSTABLE/HEATED

7A0

WITHOUT CD CHANGER/CD PLAYER

7AS

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K0

WITHOUT DIRECT TIRE PRESSURE MONITORING SYSTEM

7L3

WITHOUT START/STOP SYSTEM WITHOUT REGENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7MG

EMISSION STANDARD EU5

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7PA

PLATFORM GROUP CLASS 1

7R3

SIDE TURN SIGNALS (WHITE)

7RT

DVD (EUROPE)

7T6

NAVIGATION SYSTEM (MID)

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

8AY

RADIO NAVIGATION SYSTEM

8GU

ALTERNATOR 140 A

8JW

TWIN HEADLAMPS FOR DRIVING ON THE RIGHT (GAS DISCHARGE) W/ INTEGRATED HIGH BEAM

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N4

WINDSHIELD WIPER INTERMITTENT CONTROL WITH POTENTIOMETER (FOUR SPEEDS)

8Q6

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH DYNAMIC CORNERING LIGHT AND STATIC CORNERING LIGHT (AFS 2)

8RM

8 SPEAKERS (PASSIVE)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8T2

CRUISE CONTROL SYSTEM (CCS) ELECTRONIC

8TC

REAR FOG LAMP FOR DRIVING ON THE RIGHT

8W1

WASHER FLUID LEVEL INDICATOR

8WD

INTEGRATED FRONT FOG LAMPS

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9I0

DAYTIME HEADLIGHT MODE

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P3

BELT CONTROL, ELECTRIC CONTACT IN BUCKLE

9Q5

MULTI-FUNCTION DISPLAY WITH CONTROL

9T0

WITHOUT HEATED WASHER NOZZLES

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9U1

BRAKE PAD WEAR INDICATOR

9W0

WITHOUT CAR PHONE PREPARATION/ INSTALLATION

9WL

JACK FOR EXTERNAL AUDIO SOURCE

9Z0

OPERATING VOLTAGE 12 V

A8F

SPORTS EQUIPMENT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B14

TYPE APPROVAL COUNTRY ITALY (SAN MARINO, VATICAN CITY)

C32

OPERATING PERMIT, ALTERATION

CV0

ALLOY WHEELS 7J X 17

D91

4-CYL.TURBO DIESEL ENG.2.0 L/103 KW (4V)TDI COMMON RAIL; BASE ENGINE IS
TG3/TJ3/T5P/TU3/TU4/TL4/TP4/TM3/TW3/TR4/TS1/TN5

E0A

NO SPECIAL EDITION

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FC0

WITHOUT CUSTOMIZED INSTALLATION

G07

SHOCK ABSORPTION IN FRONT

G0L

SIX-SPEED MANUAL TRANSMISSION FOR FOUR-WHEEL DRIVE VEHICLE

GP1

VEHICLES WITH SPECIAL UPGRADE MEASURES

H6L

TIRES 225/45 R17 91W

J1D

BATTERY 380 A (72 AH)

K8G

HATCHBACK

L0L

LEFT-HAND DRIVE

L59

SUSPENSION RANGE 59 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

N0R

SEAT TRIM COVERS IN

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

QD1

NAMEPLATE FOR SALES NAME

QG1

SERVICE INTERVAL PROLONGATION

QJ3

CHROME PACKAGE (TYPE 2)

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

QR0

WITHOUT COMPASS/ROAD SIGN DISPLAY/ DYNAMIC ROAD SIGN DISPLAY

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

S2S

CONTROL (IN-PLANT)

TG3

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 03L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UF0

WITHOUT ELECTRIC INTERFACE

UG0

WITHOUT HILL START ASSIST/HILL DESCENT CONTROL/COMFORT DRIVING ASSIST

UM0

WITHOUT MARTEN REPELLER

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VK1

AIR DUCT, TYPE 1

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X4C

EQUIPMENT OPTIONS SUBSET FOR ITALY



+31

Sources de données

Nous avons vérifié 900+ sources de données dans **35 pays**