CARFAX Vehicle History Report



PEUGEOT 1007

Located in: Italy Vehicle reference: VF3KM8HZB20026205

Body type: Hatchback Gearbox type: Manual Drive: Front Fuel type: Diesel Engine size: 1398 cm3 Engine power: 50 kW / 68 hp



Number of odometer readings: 3

Number of inspection



Total number of records: 5

records: 3

Report created on: 10/02/2025 at 17:45:50



Scan QR code for current version (available until: 12/03/2025)

Quick Check		
Damage No damage reported to CARFAX	~	No issues reported
Import Not a private import	~	No issues reported
Vincoli No administrative detention or other liens reported for this vehicle (source ACI, information received on 10/02/2025). <u>What is a "Vincoli"</u>	S	No issues reported
Ipoteca No "Ipoteca" reported for this vehicle (source ACI, information received on 10/02/2025). What is an "Ipoteca"	0	No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.





Owners BETA	
Owner 1 in Italy	
Purchase year:	2005
Length of use:	3 months
Type of owner:	Commercial business
Owner 2 in Italy	
Purchase year:	2006
Type of owner:	Private individual

History information

Date	Mileage	Event
29/09/2005		Registered in Italy New owner reported Owner type: commercial
16/01/2006		New owner reported Owner type: private individual
18/05/2020	72 799 km	Inspected in Italy
10/05/2022	74091 km	Inspected in Italy
03/05/2024	75 431 km	Inspected in Italy Inspection valid until 31/05/2026
Based on data reviewed	from 22 countries in Europe a	and North America

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Environment and consumption	
Fuel type	Diesel
Weight	
Curb weight	1 243 kg
Max payload	339 kg
Gross vehicle weight	1 582 kg
Dimensions	
Length	3731 mm
Width	1 662 mm
Wheelbase	2 315 mm
Other information	
European vehicle category	M1
EU standard code	e2*2001/116*0300
Number of doors	3
Number of seats	4

CARFAX Glossary

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in flavor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Odometer

The number of kilometers displayed on the most recent odometer reading.

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.