

HYUNDAI Veloster

Located in: **Italy**

Vehicle reference:

KMHTC61DACU007333

Body type: **Hatchback**

Gearbox type: **Manual**

Drive: **Front**

Fuel type: **Petrol**

Engine size: **1591 cm3**

Engine power: **103 kW / 140 hp**

CO2 emissions in mixed driving: **142 g/km**



Accident reported:
Minor damage



Number of odometer readings: 6



Number of inspection records: 5



Total number of records: 10

Report created on:

25/02/2025 at 17:59:56



Scan QR code for [current version](#)
(available until: 08/03/2025)

Quick Check

Damage

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.

Accident

Import

Not a private import

No issues reported

Vincoli

No administrative detention or other liens reported for this vehicle (source ACI, information received on 06/02/2025). [What is a "Vincoli"](#)

No issues reported

Ipoteca


No "Ipoteca" reported for this vehicle (source ACI, information received on 06/02/2025). [What is an "Ipoteca"](#)

No issues reported

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

24/08/2013 Damage reported



Damaged area:

- Left front
- Left rear
- Rear
- Right rear

Reported on:

24/08/2013

Reported in:


Italy

Severity scale:

Minor


Damage type/cause:

Collision with another vehicle



Mileage Check

Date | Mileage
09/12/2017 | 26 391 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Vehicle age

years	months
13	1

First registration date: 30/12/2011

Inspections



Latest inspection:
19/07/2023

Inspection due date: 31/07/2025

Owners BETA

Owner 1 in Italy

Purchase year:	2011
Length of use:	9 months
Type of owner:	Commercial business

Owner 2 in Italy

Purchase year:	2012
Length of use:	12 years 1 month
Type of owner:	Private individual
Damage reported on:	24/08/2013

Owner 3 in Italy

Purchase year:	2024
Type of owner:	Commercial business

History information

Date	Mileage	Event
30/12/2011		Registered in Italy New owner reported Owner type: commercial
03/10/2012		New owner reported Owner type: private individual
24/08/2013		Accident reported in Italy
02/09/2013	12 210 km	Odometer reading reported

Date	Mileage	Event
05/12/2015	21 947 km	Inspected in Italy Inspection passed
09/12/2017	26 391 km	Inspected in Italy Inspection passed
22/07/2019	29 045 km	Inspected in Italy
22/07/2021	31 607 km	Inspected in Italy
19/07/2023	33 931 km	Inspected in Italy Inspection valid until 31/07/2025
11/11/2024		New owner reported Owner type: commercial

Based on data reviewed from 22 countries in Europe and North America

Technical details

Environment and consumption

Fuel type	Petrol
Fuel consumption in mixed driving	6.2 l/100km
CO2 emissions in mixed driving	142 g/km
EU emission standard	Euro 5

Weight

Curb weight	1 311 kg
Max payload	389 kg
Gross vehicle weight	1 700 kg

Dimensions

Length	4 220 mm
Width	1 790 mm
Wheelbase	2 650 mm

Other information

European vehicle category	M1
EU standard code	e11*2007/46*0194*01
Number of doors	5
Number of seats	4

CARFAX Glossary

Accident

This vehicle has had an accident. You will want to know the type, severity, impact location, whether or not airbags were deployed, etc. We recommend that you obtain a thorough inspection by an independent mechanic before purchasing.

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.