

**CITROEN C5**Located in: **Italy**

Vehicle reference:

**VF7RWX8ZA9L551105**Body type: **Estate**Gearbox type: **Automatic**Drive: **Front**Fuel type: **Diesel**Engine size: **2992 cm3**Engine power: **177 kW / 241 hp**

1-Owner vehicle



Accident reported



Number of odometer readings: 3



Number of inspection records: 3



Total number of records: 5

Report created on:

23/04/2025 at 16:12:38

Scan QR code for [current version](#)  
(available until: 23/05/2025)**Quick Check****Damage**

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.

**Accident****Import**


Not a private import

**No issues reported****Vincoli**No administrative detention or other liens reported for this vehicle (source ACI, information received on 23/04/2025). [What is a "Vincoli"](#)**No issues reported****Ipoteca**No "Ipoteca" reported for this vehicle (source ACI, information received on 23/04/2025). [What is an "Ipoteca"](#)**No issues reported**

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

**Damage Overview**

04/06/2013 Damage reported

**Damage type/cause:**

Collision with another vehicle

**Reported on:**

04/06/2013


**Reported in:**

Italy

## Mileage Check

Date  
**18/10/2023**

Mileage  
**115 910 km**



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

## Highlights

### Vehicle age



First registration date: 20/10/2009

### Inspections



Latest inspection:  
**18/10/2023**

Inspection due date: 31/10/2025

## Owners BETA

### Owner 1 in Italy

Purchase year:	2009
Length of use:	15 years 6 months
Type of owner:	Private individual
Damage reported on:	04/06/2013

## History information

Date	Mileage	Event
20/10/2009		Registered in Italy New owner reported Owner type: private individual
04/06/2013		Accident reported in Italy
03/10/2019	99 229 km	Inspected in Italy
11/10/2021	108 752 km	Inspected in Italy
18/10/2023	115 910 km	Inspected in Italy Inspection valid until 31/10/2025
Based on data reviewed from 22 countries in Europe and North America		

Technical details	
Environment and consumption	
Fuel type	Diesel
EU emission standard	Euro 5
Weight	
Curb weight	1 838 kg
Max payload	509 kg
Gross vehicle weight	2 347 kg
Dimensions	
Length	4 829 mm
Width	1 860 mm
Wheelbase	2 815 mm
Other information	
European vehicle category	M1
EU standard code	e2*2001/116*0360*07
Number of doors	5
Number of seats	5

## CARFAX Glossary

---

### **1-Owner vehicle**

1-Owner vehicle has been only used by one owner and consequently comes with the advantage that only one owner is responsible for its use

### **Accident**

This vehicle has had an accident. You will want to know the type, severity, impact location, whether or not airbags were deployed, etc. We recommend that you obtain a thorough inspection by an independent mechanic before purchasing.

### **Inspections**

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

### **Ipoteca**

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

### **Number of odometer readings**

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

### **Number of records**

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### **Quick Check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

### **Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

### **Vincoli**

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.