




Renault Mégane

VIN: VF1JZ3G0D44380165 Diesel 2010



Généré le 05/24/2025, 04:01 PM

Scanne pour obtenir le rapport complet

Compteur kilométrique

✓ Tout a l'air bien

Statut légal

✓ Tout a l'air bien

Dommage

✓ Tout a l'air bien

+31 Sources de données
Nous avons vérifié plus de 900 sources de données dans 35 pays

Vol

Le véhicule est-il actuellement signalé comme volé ? A-t-il été volé par le passé ? A-t-il été retrouvé ?

Aucun problème détecté

Nous n'avons trouvé aucune indication démontrant que le véhicule ait été volé.

Note

Bases de données policières. Vérification des véhicules volés effectué dans 10 pays : +4

Voici ce que nous avons vérifié :

Actuellement déclaré volé

✓ Aucun enregistrement trouvé

Volé par le passé

✓ Aucun enregistrement trouvé

Nous n'avons pas trouvé d'historique de vol pour ce véhicule.

Base de données de la police sur les véhicules volés – vérification effectuée en :

- Lituanie
- États-Unis
- Slovaquie
- Tchéquie
- Slovénie
- Hongrie
- Roumanie
- Italie
- Suède
- Canada


Compteur kilométrique

Y a-t-il des signes de compteur kilométrique trafiqué ou des différences ?



Note

- Dernier kilométrage connu : 35 561 km
- Kilométrage moyen pour des modèles similaires : 195 079 km
- 4 relevés de kilométrage trouvés



Relevés du compteur kilométrique

11/2010	11 km
11/2013	10 545 km
01/2015	12 892 km
05/2025	35 561 km

Statut légal

Le véhicule a-t-il passé le contrôle technique ? A-t-il été marqué comme mis à la casse ?



Aucun problème détecté

Aucune information sur le statut juridique de ce véhicule n'a été trouvée.

Juridique



Contrôle technique

Passé

05/2025



Italie

A passé le contrôle technique avec succès

Valide jusqu'au 05/2027

Dommage

Cette section t'aide à comprendre si le véhicule a été endommagé ou s'il a été expertisé suite à des dommages, ainsi que les estimations de coûts enregistrées (si disponibles).

✓ **Aucun problème détecté**

Registre des dommages



Des inexactitudes peuvent parfois se produire, surtout lorsqu'on vérifie des véhicules plus anciens. Les ateliers de réparation clandestins peuvent déguiser illégalement les défauts et dommages d'un véhicule. Parfois, même les plaques VIN d'un véhicule peuvent être remplacées. Nous avons diverses méthodes pour détecter ces infractions, mais il est impossible de fournir une garantie à 100%.

Catastrophes naturelles

Le véhicule a-t-il été localisé dans la zone d'une catastrophe naturelle ?

✓ **Aucun problème détecté**
Le véhicule ne s'est pas trouvé dans la zone d'une catastrophe naturelle

Valeur sur le marché


À quel prix le véhicule a-t-il été vendu par le passé ? Quel est le prix des véhicules de cette année et de ce modèle en moyenne ?

i Note

- Prix moyen sur le marché pour un tel véhicule : 3 574 €
- Méfie-toi des problèmes cachés si le véhicule est en vente pour bien moins cher que ce qu'il vaut vraiment !

Valeur d'une Renault Mégane 2010 sur le marché aujourd'hui

La valeur marchande est déterminée en examinant le prix d'un modèle de voiture particulier (fabriqué la même année) dans le pays où le rapport a été généré. Nous analysons les données des 6 derniers mois.



Émissions


Combien d'émissions de CO2 les véhicules de ce modèle/année produisent-ils ?

Avis de carVertical

Les émissions de ce véhicule sont dans la moyenne. Il sera sans doute soumis aux taxes standard sur les émissions.

Émissions de CO₂

Émission de Co₂ g/km



Spécifications et équipement

Quels sont les spécifications et l'équipement connus pour ce véhicule ?

Note

Vérifie que les spécifications et l'équipement de ce véhicule correspondent aux déclarations du vendeur.

Identification et spécifications techniques

- Marque
Renault
- Modèle
Mégane
- Description
Megane 3 / Scenic 3 (X95)
- Variante
Xmod



Type de carrosserie
Véhicule multi-usages



Année de fabrication
2010



Déplacement moteur
1,5 l



Puissance moteur
81 kW (109 hp)



Type de carburant
Diesel



Type de transmission
Manuel



Type de conduite
Traction



Nombre de portes
5



Nombre de vitesses
6



Nombre de sièges
5



Émissions de CO2
128 g/km

Équipement

D'origine, sortie d'usine

ADDITIONAL HEADLIGHTS

FOG LIGHTS (PROJAB)

ANTI-THEFT DEVICES

EQUIPMENT LEVEL OF ALARM (PREALA)

CENTER CONSOLE

SLIDING CENTRE CONSOLE WI (CSRACL)

CLIMATIC CONSTRAINT HOT COUNTRY

WO CLIMAT CONST WARM COUN (SSCCPC)

COMMERCIAL EVENT 1

COMPLEMENTARY OBJECT (SAN778)

ADDITIONAL SENSING INFORMATION

COMPLEMENTARY OBJECT (SAND58)

BRAKE CALIPER

CALIPER TYPE 1 (ETRP01)

CHASSIS TYPE

STANDARD WHEEL BASE (CHBASE)

COMMERCIAL EVENT

COMPLEMENTARY OBJECT (SANF80)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

COMMERCIAL VERSION SUPPLEMENT5

WO COMMERCIAL VERSION 1 (SVECO)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG: ITALY (TLITAL)

DAYTIME RUNNING LIGHTS

WITHOUT DAYTIME RUNNING LIGHTS (SRUNLI)

DUST PROTECTION

WITHOUT DUST KIT (SKTPOU)

ELECTRONIC STABILITY PROGRAM

DIRECTIONAL STABILITY CON (ASRESP)

EXTERIOR ACCESSORIES

WITHOUT EXTERIOR ACCESSOR (SACEXT)

FRONT AND REAR PROXIMITY RADAR

WITHOUT PROXIMITY RADAR (SRDPRO)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG + HEADA (ABLAVI)

FRONT TYRES

205/60 R16 (92)H, 6.50 J 16 - 47

GEARBOX PRODUCTION PLANT

(B) PITESTI (ROMANIA)/RENAULT MECANIQUE
ROUMANIE SRL (APV003_B)

HEADLIGHT BEAM ADJUSTMENT

MANUALADJUSTMENT OF HEADL (RGSITM)

INSTRUMENT PANELS

INSTRUMENT PANEL 06 (TBOR06)

INTERNAL NAME

NO NAME (SSAPEL)

LEVEL OF NAVIGATION AID

LEVEL 1 TYPE 1 NAVIGATION (NAV1G1)

LUGGAGE BOX

W/O LUGGAGE BOX (SRANCF)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

MISCELLANEOUS BENEFITS CINQUO

COMPLEMENTARY OBJECT (SANE24)

MISCELLANEOUS BENEFITS QUATRO

LEATHER PRESTATION BOSE (SSPRBO)

MISCELLANEOUS BENEFITS TER

COUNTER UNIT

KILOMETRES (KM)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

DOOR OPENING REMOTE CONTROL TYPE

433 MHZ NORMAL DOOR OPENI (SOP01C)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

ENGINE PRODUCTION PLANT

(D) VALLADOLID MOTORES (SPAIN) (APV002_D)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 02 (RET02)

FRONT SEAT TYPE

FRONT SEAT TYPE N 06 (SGAV06)

FRONT SPORT SEATS

W/O SPORT SEAT (SSAVSP)

GEAR SHIFT INDICATOR

COMPLEMENTARY OBJECT (SANE84)

HARNESS MODULAR MANAGEMENT1

MODULAR MANAGEMENT A 064 (GMA064)

HEADLIGHT WASHER

WITHOUT HEADLIGHT-WASHER (SLAVPH)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 01 (HARM01)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (X951MO)

LIGHTING GROUND

FRONT+REAR LIGHTG GROUND (ECCVVVR)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

MARKETING VERSION

COMMERCIAL VERSION (VEC183)

MISCELLANEOUS BENEFITS NINE

COMPLEMENTARY OBJECT (SANE68)

MISCELLANEOUS BENEFITS SIXT

COMPLEMENTARY OBJECT (SANE26)

NAVIGATION MAP

WITHOUT SERVICE TER (SPRTER)

ON-BOARD WARRANTY/SERVICES

WO ON BOARD DOCUMENTATION (SSCEDC)

PASSENGER COMPARTMENT HEATING TYPE

REGULATED AIR CONDITIONIN (CAREG)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN593)

RADIOS DELIVERY

COMPLEMENTARY OBJECT (SANE74)

REAR SCREEN BLIND

REAR BLIND 01 (RIDO01)

REAR TYRES

205/60 R16 (92)H, 6.50 J 16 - 47

ROAD SEVERITY

NORMAL SUSPENSION (SUSNOR)

ROOM LIGHTING

WITH READING LIGHT ON ROO (SPOTLC)

SEAT COVERS

FABRIC SEAT-LINING N 09 (DRAP09)

SEAT TRIMS

VELVET CLOTH (DRA)

SERVICE COUNTRY

WITHOUT SERVICE COUNTRY (SSPRPT)

SPARE WHEEL

NORMAL SPARE (RSNORM)

SPORT PACKAGE SUPPLEMENT

WITHOUT SPORT EQUIPMENT P (SSCPKS)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58Y)

STEERING WHEEL POSITION

LEFT (DG)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE2 (TAV27)

TECHNICAL EVOLUTION

COMPLEMENTARY OBJECT (SANG02)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

STANDARD MAPPING (MAPSTD)

PARKING BRAKE TYPE

ELECTRICAL PARKING BRAKE (FPASS)

PASSENGER COMPARTMENT THERMAL REQUIREMENT

PASSENGER COMPARTMENT THERMAL
REQUIREMENT 3 (THABT3)

PRESTATION EIGHT

COMPLEMENTARY OBJECT (SANE44)

REAR HEADREST TYPE

FULL REAR HEAD RESTRAINTS (ATARPH)

REAR SEAT TYPE

WITH REAR SEATS (SJAR)

REAR WINDOW CONTROL

ANTI-PINCHING PULSED (LVARIP)

ROOF RACK/BARS

NO ROOF BARS (SBARTO)

ROUTING SHEETS COUNTRY

ITALY (ITAL)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

SEATS: 3RD ROW

0 SEAT - THIRD ROW SEATS (OP3RAN)

SMOKER'S ACCESSORIES

WITH SMOKER ACCESSORIES (AVCACF)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 2 (TAR22)

STEERING WHEEL MATERIAL

LEATHER STEERING WHEEL (VLCUIR)

STRIPPING

WITHOUT STRIPPING (SSDECA)

TECHNICAL ENVELOPES (SEE OVAL PLATE)

ENVIRONNEMENTAL CONSTRAIN (CEE1)

TELEMATIC SYST FOR CUSTOMER INCI

W/O TELEMATIC SYSTEM INC (SSTINC)

TYPE OF HEADLIGHTS

WITHOUT DISCHARGE LAMPS (SLDECH)

TYPE OF HOOPS + TARPAULIN

WITHOUT ROLL BAR (SSARCE)

TYRE PRESSURE DETECTION

WITHOUT TYRE PRESSURE DET (SDPRPN)

UNIVERSAL INTERCONNECT FUNCTION

COMPLEMENTARY OBJECT (SANE70)

VARIOUS ADDITIONAL FEATURES

SAFETY EQUIPMENT PACK 2 (PRESE2)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

VEHICULE TRANSFORMATION

WO VEHICULE TRANSFORMATIO (SSTRFV)

WATER PROTECTION

WO RAIN FORD RIVER KIT (SKTPGR)

WHEEL RIM TYPE

17 ALUMINIUM WHEEL RIMS 1 (RALU17)

WIND DEFLECTOR NET

W/O WIND DEFLECTOR NET (SAREMA)

WINDSCREEN TINT

ATHERMAL WINDSCREEN (ANTI (PBRA)

TYPES OF RADIOS

RADIO 04 (RAD04)

UNDERBODY PROTECTION

WO ANTIGRIT PROTECTION (SKTGRV)

UTILITY ADAPTATION COVER

WITHOUT ADAPTATION (SAN164)

VARIOUS FUNCTIONS

WITHOUT PRODUCT EQUIPMENT (SSPTPR)

VEHICLE PRODUCTION PLANT

(D) DOUAI (FRANCE) (APV001_D)

VENTILATION FLAP

REAR SEATS FOOTWELL AIR VENT (AERA01)

WHEEL DISC PROTECTION

WITHOUT PROTECTIVE REAR B (SPRODI)

WHEELS RIMS

BASE WHEEL (RNBASE)

WINDOW TINT

TINTED WINDOWS (VT)

WIPER START-UP TYPE

AUTOMATIC LIGHTS + WINDSCREEN WIPER (ALEVA)

Chronologie

3 enregistrements trouvés

La chronologie des enregistrements pour ce véhicule

Derniers enregistrements

11/2010 🌐 Pays inconnu



Fabrication

Le pays (ou l'État) indique soit le lieu de fabrication, l'usine d'assemblage ou l'adresse d'enregistrement du fabricant. La date peut être approximative.

03/2011 🇮🇹 Italie



Première immatriculation

Cet enregistrement représente le fait d'un événement administratif. Il pourrait s'agir d'un changement de propriétaire, de documents, etc.

05/2025  Italie

  **A été inspecté**

Une inspection technique (aussi connu sou le nom de MOT, contrôle technique, ou test de contrôle des émissions) a été enregistré. Les tests passés avec succès et ceux qui ont échoué peuvent être inclus.



Sources de données

Nous avons vérifié plus de 900 sources de données dans **35 pays**