



Vehicle History Report

VOLKSWAGEN Golf

Vehicle reference:

WVWZZZ1JZYB079018

Body type:
Hatchback

Gearbox type:
Manual

Engine size:
1781 cm³

Fuel type:
Petrol

Combustion engine power:
110 kW / 150 hp

Drive:
Front

Report created on:
23/07/2025 at 12:06:12



Scan QR code for [current version](#)

Located in Italy



Vehicle age

**25 years
6 months**

How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



Quick Check

Damage

No damage reported to CARFAX

No issues reported

Import

Not a private import

No issues reported


Damage Overview



No damage reported: There has been no damage reported for this vehicle

Mileage Check

Date | Mileage
09/03/2024 | 114 938 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



Owner(s) in Italy

Purchase year: **2000**

There is no more information available about one or more consecutive owners.

Owner(s) in Italy

Purchase year: **2007**

There is no more information available about one or more consecutive owners.

History information

Date	Mileage	Event
19/01/2000		Registered in Italy
11/10/2007		New owner reported
13/05/2008		Inspected in Italy Inspection passed
18/03/2014		Inspected in Italy Inspection passed
04/03/2016	104 000 km	Inspected in Italy Inspection passed
21/03/2018	107 573 km	Inspected in Italy Inspection passed
03/03/2020	111 500 km	Inspected in Italy Inspection passed

Date	Mileage	Event
05/03/2022	112 699 km	Inspected in Italy Inspection passed
09/03/2024	114 938 km	Inspected in Italy Inspection passed Inspection valid until 09/03/2026
Based on data reviewed from 22 countries in Europe and North America		

Technical details	
Engine and performance	
Fuel type	Petrol
Combustion engine power	110 kW / 150 hp
Weight	
Curb weight	1 399 kg
Max payload	381 kg
Gross vehicle weight	1 780 kg
Dimensions	
Length	4 149 mm
Width	1 735 mm
Wheelbase	2 500 mm
Other information	
European vehicle category	M1
EU standard code	e1*98/14*0071
Number of seats	5

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.