



## Vehicle History Report

### RENAULT Twingo

Vehicle reference:

**VF1C068A524045882**

Body type:  
**Hatchback**

Gearbox type:  
**Manual**

Engine size:  
**1149 cm<sup>3</sup>**

Fuel type:  
**Petrol**

Combustion engine power:  
**43 kW / 58 hp**

Drive:  
**Front**

Report created on:  
24/07/2025 at 17:43:12



Scan QR code for [current version](#)

Located in Italy



Vehicle age

**24 years  
6 months**

1-Owner vehicle



### How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



#### Quick Check

##### Damage

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.

**● Accident**


##### Import

Not a private import

**● No issues reported**

## Damage Overview

08/06/2006 Damage reported



Damaged area:

- Rear

Severity scale:

Minor

Damage type/cause:

Collision with another vehicle

Reported on:

08/06/2006

Reported in:

Italy


### SEVERITY SCALE



## Mileage Check

Date  
27/01/2021

Mileage  
83 214 km



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

**Owner 1 in Italy**

Purchase year:	2001
Length of use:	24 years 6 months
Damage reported on:	08/06/2006

**History information**

Date	Mileage	Event
16/01/2001		Registered in Italy New owner reported
08/06/2006		Accident reported in Italy
29/06/2006	30 867 km	Odometer reading reported
25/01/2019	75 228 km	Inspected in Italy
27/01/2021	83 214 km	Inspected in Italy

Based on data reviewed from 22 countries in Europe and North America

Technical details	
Engine and performance	
Fuel type	Petrol
Combustion engine power	43 kW / 58 hp
Weight	
Curb weight	895 kg
Max payload	335 kg
Gross vehicle weight	1 230 kg
Dimensions	
Length	3 433 mm
Width	1 630 mm
Wheelbase	2 340 mm
Other information	
European vehicle category	M1
EU standard code	e2*98/14*0071
Number of doors	3
Number of seats	4

## CARFAX Glossary

### 1-Owner vehicle

1-Owner vehicle has been only used by one owner and consequently comes with the advantage that only one owner is responsible for its use

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

### Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

### Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

**Severity scale - Severe**

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.