



Vehicle History Report

TOYOTA RAV4

Vehicle reference:

JTMBB31V606037128

Body type:
SUV/MPV

Gearbox type:
Manual

Engine size:
2231 cm³

Fuel type:
Diesel

Combustion engine power:
130 kW / 177 hp

Drive:
AWD

Report created on:
25/07/2025 at 17:24:43



Scan QR code for [current version](#)

Located in Italy



Vehicle age

**18 years
8 months**

How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



Quick Check

Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

● Damage


Import

Not a private import

● No issues reported

Damage Overview

13/02/2020 Damage reported



Damaged area:

- Left
- Left rear
- Rear
- Roof

Reported on:

13/02/2020

Reported in:


Italy

Severity scale:

Minor


Damage type/cause:

Not available



Mileage Check

Date | Mileage
23/11/2022 | 110 292 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



Owner(s) in Italy

Purchase year: **2006**

There is no more information available about one or more consecutive owners.

Owner(s) in Italy

Purchase year: **2019**

Damage reported on: **13/02/2020**

History information

Date	Mileage	Event
09/11/2006		Registered in Italy
08/11/2010		Inspected in Italy Inspection passed
19/11/2012		Inspected in Italy Inspection passed
18/11/2014		Inspected in Italy Inspection passed
15/11/2016	67 930 km	Inspected in Italy Inspection passed
12/11/2018	74 809 km	Inspected in Italy Inspection passed
07/11/2019		New owner reported
13/02/2020		Damage reported in Italy

Date	Mileage	Event
13/11/2020	87 651 km	Inspected in Italy
23/11/2022	110 292 km	Inspected in Italy
Based on data reviewed from 22 countries in Europe and North America		

Technical details	
Engine and performance	
Fuel type	Diesel
Combustion engine power	130 kW / 177 hp
Environment and consumption	
EU emission standard	Euro 4
Weight	
Curb weight	1 700 kg
Max payload	490 kg
Gross vehicle weight	2 190 kg
Dimensions	
Length	4 395 mm
Width	1 855 mm
Wheelbase	2 560 mm
Other information	
European vehicle category	M1
EU standard code	e6*2001/116*0105
Number of doors	5
Number of seats	5

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.