

VOLKSWAGEN Polo GTI

Located in: **Italy**

Vehicle reference:

WVWZZZ9NZ7Y056449

Body type: **Hatchback**

Gearbox type: **Manual**

Drive: **Front**

Fuel type: **Petrol**

Engine size: **1781 cm³**

Engine power: **110 kW / 150 hp**



1-Owner vehicle



Accident reported:
Minor damage



Number of odometer
readings: 5



Number of inspection
records: 3



Total number of
records: 8

Report created on:

02/05/2025 at 17:59:28



Scan QR code for [current version](#)
(available until: 01/06/2025)

Quick Check


Damage

This vehicle has had an accident. Have it inspected by a mechanic before purchasing.



Import

Not a private import




Vincoli

No administrative detention or other liens reported for this vehicle (source ACI, information received on 02/05/2025). [What is a "Vincoli"](#)



Ipoteca


No "Ipoteca" reported for this vehicle (source ACI, information received on 02/05/2025). [What is an "Ipoteca"](#)



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.

Damage Overview

22/09/2009 Damage reported



Damaged area:

- Left
- Left front

Severity scale:

Minor

Damage type/cause:


Collision with another vehicle

Reported on:


22/09/2009

Reported in:

Italy



31/07/2011 Damage reported



Damaged area:

- Left rear

Severity scale:

Minor

Damage type/cause:


Collision with another vehicle

Reported on:

31/07/2011


Reported in:

Italy



Mileage Check

Date | Mileage
30/09/2019 | **124 000 km**



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Highlights

Vehicle age



First registration date: 14/09/2007

Inspections



Latest inspection:
09/11/2023

Inspection due date: 30/11/2025

Owners BETA

Owner 1 in Italy

Purchase year:	2007
Length of use:	17 years 7 months
Type of owner:	Private individual
Damage reported on:	31/07/2011, 22/09/2009

History information

Date	Mileage	Event
14/09/2007		Registered in Italy New owner reported Owner type: private individual
22/09/2009		Accident reported in Italy
12/10/2009	40 830 km	Odometer reading reported
31/07/2011		Accident reported in Italy
08/08/2011	69 381 km	Odometer reading reported
30/09/2019	124 000 km	Inspected in Italy
04/10/2021	128 044 km	Inspected in Italy
09/11/2023	133 815 km	Inspected in Italy Inspection valid until 30/11/2025

Based on data reviewed from 22 countries in Europe and North America

Technical details

Environment and consumption

Fuel type	Petrol
EU emission standard	Euro 4

Weight

Curb weight	1 298 kg
Max payload	402 kg
Gross vehicle weight	1 700 kg

Dimensions

Length	3 915 mm
Width	1 650 mm
Wheelbase	2 452 mm

Other information

European vehicle category	M1
EU standard code	e1*2001/116*0174*18
Number of seats	5

CARFAX Glossary

1-Owner vehicle

1-Owner vehicle has been only used by one owner and consequently comes with the advantage that only one owner is responsible for its use

Accident

This vehicle has had an accident. You will want to know the type, severity, impact location, whether or not airbags were deployed, etc. We recommend that you obtain a thorough inspection by an independent mechanic before purchasing.

Inspections

Periodic examination of a vehicle to ensure compliance with road worthiness, emissions and safety requirements.

Ipoteca

"Ipoteca" is a security in favor of a creditor over a vehicle belonging to the debtor: creditors can protect themselves by taking out an "Ipoteca" on the vehicle. "Ipoteca" creates a lien on the vehicle without preventing the owner from using and disposing/selling the vehicle. The mortgage, once registered, follows the vehicle until the secured claim is extinguished, even if there are subsequent transfers of ownership.

Number of odometer readings

The periodic mileage as reported to CARFAX. A greater number of odometer readings increases the likelihood of correct mileage.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

Vincoli

There is an administrative impoundment or upcoming seizure, what means that the car may not be used or sold. Reasons for a seizure, can be drunk driving, not paid taxes or no valid insurance.