

## TOYOTA RAV4

Vehicle reference:

**JTMBB31V40D097128**Body type:  
SUV/MPVGearbox type:  
AutomaticEngine size:  
2231 cm<sup>3</sup>Fuel type:  
DieselCombustion engine power:  
110 kW / 150 hpDrive:  
AWD

Report created on: 14/01/2026 at 17:46:37

Scan QR code for [current version](#)

Located in Italy



Vehicle age

**13 years  
10 months**

### How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



#### Quick Check

##### Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

**● Damage**


##### Import

Not a private import

**● No issues reported**

## Damage Overview

11/03/2018 Damage reported



**Damaged area:**

- Rear

**Severity scale:**

**Minor**

**Damage type/cause:**


Collision with another vehicle

**Reported on:**

11/03/2018

**Reported in:**

Italy



## Damage Glossary

### Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

## Mileage Check

Last odometer reading

**97 428** km


Reported on: 27/03/2025

Average mileage

**7 434** km/year

Average mileage for similar cars

**13 497** km/year



**No issues indicated:** The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



**Owner 1 in Italy**

Purchase year:	<b>2012</b>
Length of use:	<b>2 years 11 months</b>
Type of owner:	<b>Commercial business</b>

**Owner 2 in Italy**

Purchase year:	<b>2015</b>
Length of use:	<b>3 years 3 months</b>
Type of owner:	<b>Private individual</b>
Damage reported on:	<b>11/03/2018</b>

**Owner 3 in Italy**

Purchase year:	<b>2018</b>
Type of owner:	<b>Private individual</b>

**History information**

Date	Mileage	Event
21/02/2012		Registered in Italy New owner reported Owner type: commercial
18/02/2015		New owner reported Owner type: private individual

<b>Date</b>	<b>Mileage</b>	<b>Event</b>
24/02/2016	18 966 km	Inspected in Italy Inspection passed
11/03/2018		Damage reported in Italy
13/03/2018	38 646 km	Inspected in Italy Inspection passed
20/04/2018	40 674 km	Odometer reading reported
31/05/2018		New owner reported Owner type: private individual
05/01/2021	62 718 km	Inspected in Italy
27/03/2025	97 428 km	Inspected in Italy Inspection valid until 31/03/2027
Based on data reviewed from 22 countries in Europe and North America		

## Technical details

### Engine and performance

Fuel type	Diesel
Combustion engine power	110 kW / 150 hp

### Environment and consumption

EU emission standard	Euro 5
----------------------	--------

### Weight

Curb weight	1 705 kg
Max payload	485 kg
Gross vehicle weight	2 190 kg

### Dimensions

Length	4 365 mm
Width	1 855 mm
Wheelbase	2 560 mm

### Other information

European vehicle category	M1
EU standard code	e6*2001/116*0105*08
Number of doors	5
Number of seats	5

## CARFAX Glossary

### Average Mileage

Average Mileage is not the actual odometer reading for this car, but an estimate of how many kilometers an average car of this make, model, fuel type and age would be expected to have if used solely for personal use. The actual mileage for this particular car will indicate if it has been driven more or less than average and may be a factor to help you determine its value

### Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

### Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Severity scale - Minor**

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

**Severity scale - Moderate**

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

**Severity scale - Severe**

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.