

SUBARU Impreza

Vehicle reference:

JF1GP3LC5CG004703Body type:
EstateGearbox type:
AutomaticEngine size:
1600 cm³Fuel type:
PetrolCombustion engine power:
84 kW / 114 hpDrive:
AWDCO2 emissions in mixed
driving:

146 g/km



Report created on: 04/04/2026 at 17:21:42

Scan QR code for [current version](#)

Quick Check

Damage

No damage reported to CARFAX

No issues reported**Import**

Not a private import

No issues reported

Located in Italy



Vehicle age

**13 years
4 months**

Damage Overview


**No damage reported to CARFAX**

Please keep in mind that not every damage or accident gets reported to us.

Mileage Check

Date
18/11/2022

Mileage
28 125 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



Owner(s) in Italy

Purchase year: **2012**

There is no more information available about one or more consecutive owners.

Owner(s) in Italy

Purchase year: **2013**

There is no more information available about one or more consecutive owners.

History information

Date	Mileage	Event
30/11/2012		Registered in Italy
08/04/2013		New owner reported
07/11/2018	24 939 km	Inspected in Italy
04/11/2020	26 417 km	Inspected in Italy
18/11/2022	28 125 km	Inspected in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Technical details	
Engine and performance	
Fuel type	Petrol
Combustion engine power	84 kW / 114 hp
Environment and consumption	
Fuel consumption in mixed driving	6.3 l/100km
CO2 emissions in mixed driving	146 g/km
EU emission standard	Euro 5
Weight	
Curb weight	1 530 kg
Max payload	410 kg
Gross vehicle weight	1 940 kg
Dimensions	
Length	4 450 mm
Width	1 780 mm
Wheelbase	2 635 mm
Other information	
European vehicle category	M1
EU standard code	e1*2007/46*0597*01
Number of doors	5
Number of seats	5

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions.](#)